

Low Pressure Screw Pump

Application

The Calibration hand pump is a low air pressure source with the ability to easily adjust and stabilise

The Pump is used for calibration pressure transducers, precision pressure gauges along with standard or master indicators

Specifications

Range : Generation of Pressure : 2/7 bar

Generation of vacuum : - 0.8 Bar

Medium : Dry Air

End Connection For Master : 1/4" BSP

Flexible Hose With 1/4" BSP (F) For Gauge to be Calibrated



Accessories

- Set of Washers & O rings: 1/8", 1/4", 3/8", 1/2" - 6 Nos. each
- Set of Adaptors:
1/4" BSP (M) x 1/8" BSP (F), 3/8" BSP (F), 1/4" BSP (F)

Dimension

H - 16.5 cm

W - 10 cm

The Pump is fitted with 1/2 mtr 4 mm Nylon hose with end connection 1/4" BSP (F). Other end connection 1/4" BSP

Master Gauge (Optional)



HP Series
(0.1 Accuracy)



LC Series
(0.5 Accuracy)